


(EXAMPLE 1) CONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION) / DISCONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION)



(EXAMPLE 2) CONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION) / DISCONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION)



(EXAMPLE 3) CONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION) / DISCONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION)



(EXAMPLE 4) CONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION) / DISCONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION)

